



FMO3.5
3.5 GALLON FOAM MARKING SYSTEM

Sprayer Specialties Foam Markers

Fully Functional 3.5 Gallon Foam Marker
For Turf and Lawn Applications

- Left / Right Control
- Substantial Running Time

| Part# | Description | Price |
|---------|---------------------|------------|
| FMO-3.5 | 3.5 Gal Foam Marker | \$2,355.92 |

FOAM MARKER PARTS & ACCESSORIES

PARTS & UPGRADES FOR FMO & HO-FMO SYSTEMS



STAYFOAM: 120

Stays on the ground on days
when other foams disappear!

Mix Rate 120 Gal. Water:1 Gal. StayFoam

| Part# | Description | Price |
|--------|------------------|-------------|
| STF120 | Foam Concentrate | \$93.63/gal |



HO-FMO-FCA100-34-100 \$45.98
FMO-FCA-34-12-100 \$45.97



FMO-BOOT100
\$60.30



FMO-SOCK
\$23.71



FMO-BTF
\$40.90

**CATALOG IS LIST PRICE
PLEASE APPLY DISCOUNT**

| Part# | Description | Price |
|----------------------|--|------------|
| FMO-COMP | 12 Volt Thomas Air Compressor | \$806.58 |
| FMO-CF | Air Filter Assembly for FMO-COMP; Includes Cap, Body & Element (660584) | \$32.91 |
| HO-FMO-CRK | HO Compressor Repair Kit (Diaphragm, Filter, Gasket & Check Valve)(SK927) | \$139.17 |
| FMO-CRK | Compressor Repair Kit (Diaphragm, Filter, Gasket & Check Valve)(SK107B) | \$110.71 |
| FMO-NV | Needle Valve, Liquid Flow Control (will retrofit) | \$99.24 |
| FMO-BOOT100 | Standard Boot for FMO-25, 1" Hose Barb, Sock & Fitting | \$60.30 |
| FMO-BTF | Standard Boot for FMO-25, Rubber Funnel ONLY | \$40.90 |
| FMO-SOCK | Foam Retaining Sock for Boot Bottom | \$23.71 |
| FMO-CVA | Air Check Valve Assembly | \$23.87 |
| FMO-YBA | 3/8" Hose "Y" Assembly | \$24.81 |
| FMO-FCA34-12-100 | Foam Chamber, New Style, 3/4" Chamber, 1/2" Barb Inlet, 1" Barb Elbow Outlet | \$45.97 |
| FMO-HRNS-NS | New Style Control Box with Dial Control & 10' Harness (063-0171-812) | \$930.86 |
| FMO-HRNS-EXT-NS | 12' Extension for Newer Control Box with Dial Control (115-0171-048) | \$159.09 |
| FMO-HRNS-S-NS | Secondary / Foamer Side of Harness (115-0171-035) | \$131.02 |
| FMO-HRNS | Wiring Harness, Complete (Before February 1999) | \$313.34 |
| FMO-HRNS-EXT | 10' Harness Extension (Before February 1999) | \$107.70 |
| FMO-HRNS-CB | Control Box Side of Harness (Before February 1999) | \$194.47 |
| FMO-HRNS-S | Secondary / Foamer Side of Harness (Before February 1999) | \$67.08 |
| HO-FMO-FCA100-34-100 | Foam Chamber, HO-New Style, 3/4" Hose Barb Inlet, 1" Barb Elbow Outlet | \$45.98 |
| HO-FMO-COMP-T | 12 Volt High Output Air Compressor w/ Internal Filter | \$929.48 |
| HO-FMO-CRK | HO Compressor Repair Kit (Diaphragm, Filter, Gasket & Check Valve)(SK927) | \$139.17 |
| HO-FMO-COMP-TCF | Air Filter Assembly for HO-FMO-COMP; Includes Cap, Body & Element (660587) | \$39.49 |
| 26324-144F | TeeJet Foamer Solenoid | \$93.63 |
| PK-AB144A-1-3-KIT | TeeJet Foamer Solenoid Repair Kit | \$41.08 |
| STF120 | StayFoam:120, Foam Concentrate; 1 Gallon | \$93.63 |
| K34 | 3/4" Style K Suction Hose | \$1.91 /ft |
| VSG12 | 1/2" Vinyl Sight Gauge | \$1.68 /ft |
| 8000-941-260 | Shurflo 12Volt 100 PSI Pump | \$209.02 |